



NUMBER: 31-002-18

GROUP: 31 - Collision Bulletins

DATE: November 10, 2018

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 31-002-14, DATED SEPTEMBER 24, 2014, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS**** AND INCLUDES UPDATED INFORMATION.**

SUBJECT:

Safety Certification and Tire Pressure Label Replacement Guidelines

DISCUSSION:

FCA has chosen ECS Automotive Concepts to manufacture late model original equipment licensed vehicle information labels for the collision repair industry. Replacement of the Safety Certification label and Tire Pressure label allows a collision repair facility to put a car one step closer to pre-loss condition.



Fig. 1

Tire Label

For more information, visit www.ecsvin.com** or call 1-855-ECSVIN (U.S. dealers) or 1-636-536-2221 (Canadian dealers)**

POLICY:

Information Only